

CrossCountry HST Diagrams

May 19th to December 2009

(Weekends to early September)

Diagram	Mondays to Fridays	Saturdays	Sundays
XC001	EC 0608 EDB-PMH 1521 PMH-LDS NL	NL 0800 MAP-PTN 1347 PTN-MAP NL	NL 0830 LDS-PMH 1521 LDS-YRK NL WKS XC002 Mo
XC002	NL 0600 LDS-PMH 1221 PMH-GLC EC	EC 0700 GLC-NQY 1958 NQY-PMH LA	LA 0905 PMH-NQY 1130 NQY-EDB EC WKS XC003 Mo
XC003	EC 0632 DUN-PMH 1721 PMH-LDS NL	NL 0600 LDS-PMH 1221 PMH-GLC EC	EC 0850 EDB-PMH 1821 PMH-LDS NL WKS XC004 Mo
XC004	NL 0632 YRK-PMH 1321 PMH-EDB EC	EC 0642 NCL-PNZ 1625 PNZ-LDS NL	NL 0809 LDS-PMH 1421 PMH-EDB EC WKS XC005 Mo
XC005	<u>FX</u> EC SPARE / MTCE <u>FO</u> 1306 EDB-PMH LA	LA 0630 PMH-NQY 0930 NQY-DUN EC	EC SPARE / MTCE EC WKS XC001 Mo



Key:

DUN-Dundee
EDB-Edinburgh
LDS-Leeds
YRK-York
NCL-Newcastle
GLC-Glasgow C.
MAP-Manchester Piccadilly
PMH-Plymouth
PNZ-Penzance
PTN-Paignton
NQY-Newquay

SUNDAY TIMINGS SUBJECT TO ENGINEERING WORK